

## APPENDIX 2

### Flood Risk Management Capital Expenditure

#### Harbours

Location	Improvement Works Description	Estimated Cost (£)
Cullen	Localised Pier repairs to timber piles and Wave Protection	£300,000
Findochty	Works to sheet piles at harbour entrance	£147,000
	<b>Total</b>	<b>£447,000</b>

#### Flood Risk Management and Coastal Protection

Location	Improvement Works Description	Estimated Cost (£)
----------	-------------------------------	--------------------